
NiGLON Installation **Essentials**

BBC5 Backbox Repair Clip

Back Box Repair Clip is a two part calibrated metal clip, designed to repair lug failures on metal back boxes, without the need to remove and replace the whole back box. This product is a time, labour, and cost saving solution; it is the most professional back box lug repair available on the market today.

Technical Specifications	
How it works	Fully remove the damaged lug, clear external edge and straighten box side. Apply pressure and pushto secure, by hand or with pliers. Do not strike oruse hammers, as this will compromise and damage the component andn do not over tighten screws on faceplate
Usage	Replace a broken lug in a metal back box.
Kit contents	A unique push together 2 piece clip system, overall dimensions 18mm x 8mm, 0.25mm. Comprisinga sprung, calibrated and tensioned steel plate against a 1mm galvanised metal M3.5 thread, clips securely to a back box, allowing face plate adjustment and levelling.
Secondary use	British Standards and International Electrotechnical Commissions policies: BS 4662 BS EN 60670
IPO Design Registration No.	4033473



ESOE. Whilst every care has been take in ensuring the accuracy of this document, the Supplier accepts no liability whatsoever for any eventuality arising from errors or omissions within its catalogues, brochures, printed media or within any online presence.

0121 711 1990 NiGLON sales@niglon.co.uk | www.niglon.co.uk